

Product Notice No. 152

PSTN E1/T1 Framer and Line Interface Component Replacement on 1610 Blade Family

Notice Audience:

This Product Notice is intended for users of Mediant 2000, Mediant 5000/TP-1610, Mediant 8000/TP-1610, TP-1610 and SB-1610.

Notice Subject:

The PSTN Framer and Line Interface component on the TP-1610 blade has reached end-of-life (EOL).

The PSTN Framer and Line Interface component replacement requires a software update which has been included on the various software releases listed below.

Notice Date:

June 25, 2012

Notice Effective Date:

June 25, 2012

Last Time Buy:

Customers wishing to submit Last Time Buy (LTB) are requested to do so by **November 30, 2012.** Last Time Ship date will be **December 31, 2012**. Please note that only limited stock is available for LTB. When submitting an LTB order, please add the following note "Supply with Framer Version 1.3", to the Purchase Order.

Notice Details:

- The current PSTN E1/T1 Framer and Line Interface component (Infineon PEB22554 Quad FALC v1.3) was
 declared by Infineon (component vendor), as end-of-sale in February 2009. AudioCodes has now reached end
 of stock of this component. AudioCodes expect stock to be depleted by December 31, 2012, all Mediant 2000,
 Mediant 5000, Mediant 8000, SB-1610 blades and TP-1610 blades shipped, will include the replacement PSTN
 E1/T1 Framer and Line Interface component (Infineon PEB22554 Quad FALC v3.1), which requires a software
 upgrade as listed below.
- 2. Users of software versions older than the ones listed below should upgrade to at least the version specified under the "Specific cmp/System Software Version" column.



Note: Mediant 5000/1610 and Mediant 8000/1610 refer to Mediant 5000 or Mediant 8000 systems installed with TP-1610 blades.



Product Migration:

Mediant 2000 / TP-1610 using SIP Control Protocol:

Major Software Version	Specific cmp Software Version	Notes
5.2	5.20A.052.003	Minimum version
5.4	5.40A.043.002	Minimum version
5.6	5.60A.037.001	Minimum version
5.8	5.80A.056.000	Minimum version
6.0	6.00A.032.000	Minimum version
6.2 and beyond	6.2 GA and beyond	6.2 GA and all versions beyond this version include support for the new framer device.

Mediant 2000 / TP-1610 using MGCP, MEGCO or TPNCP Control Protocol:

Major Software Version	Specific cmp Software Version	Notes
5.2	5.20.069.005	Minimum version
5.4	5.40.062.005	Minimum version
5.6	5.60.046.004	Minimum version
5.8	5.80.047.004	Minimum version
6.0	6.00.013.004	Minimum version
6.2	6.20.001.003	Minimum version
6.4 and beyond	6.4 GA and beyond	6.4 GA and all versions beyond this version include support for the new framer device.

Mediant 5000 or Mediant 8000 with TP-1610 using SIP, MGCP or MEGCO Control protocol:

Major Software Version	Specific System Software Version	Notes
5.2	5.2.110	Minimum version

Affected Product Family / Part Numbers:

Part Number	Notes
M2K/	Mediant 2000 product line
M2K-Dn	* where n is any number between 1-10
SB1610A/	SB-1610 and TP-1610 blades
TP1610B/	
MG5000/REDUN/1610	Mediant 5000 or Mediant 8000 systems installed with TP-1610.
MG8000/REDUN/1610	
HW/TP1610/	
HW/TP1610B/	

^{/... -} Refers to any part numbers with the stated prefix listed above.

www.audiocodes.com/info Website: www.audiocodes.com