

# Product Notice No. 0176

## Version 6.6 Maintenance Release

### Notice Subject:

AudioCodes has released Version 6.6 maintenance release.

### Notice Date:

June 4, 2013.

### Notice Effective Date:

Immediate.

### Affected Products:

- Mediant Series
- MP-1xx Series

### Notice Details:

AudioCodes has released a 6.6 version update -- **6.60A.228.011** -- for the Mediant and MP-1xx product lines, and recommends users of earlier 6.6 versions to upgrade to this release. This release is available for download at <http://www.audiocodes.com/downloads>.

A partial list of bug fixes as well as feature enhancements are described below; the complete list is available for download at the URL given above.

#### Fixed Issues:

1. Under certain circumstances, the device may experience an autonomous reset. This issue is relevant only to customers running 6.6 versions earlier than (not including) 6.60A.219.001.
2. In SBC applications (all products), T.38 Fax Forwarding functionality doesn't work. This issue is relevant to customers running software versions earlier than (not including) 6.60A.224.005.
3. SIP BYE messages expose the topology in the SIP Contact header. This issue is relevant for software versions earlier than (not including) 6.60A.228.008.

#### Feature Enhancements:

1. Additional performance monitoring counters are now supported through the Web interface and SNMP for collecting call duration and out-of-resource events for Trunk Groups.
2. The addition and removal of authorized SIP User Agents can now be done through CLI.
3. Test calls to check the link can now be initiated through the Web interface.