Product Notice No.: 0189

RS-232 Cable No Longer Supplied with Mediant 800 and Mediant 1000B

Notice Subject:

The RS-232 cable is no longer supplied with the Mediant 800 and Mediant 1000B product series (Gateway-SBC and MSBR).

Notice Date:

September 10, 2013.

Notice Effective Date:

- Mediant 1000B - July, 2013
- Mediant 800 - September, 2013

Notice Details:

The Mediant 800 and Mediant 1000B product series (Gateway-SBC and MSBR) are now shipped without the RS-232 cable. The RS-232 cable was included in the product's package for debugging purposes during the product's initial selling phase.

Customers wishing to purchase the RS-232 cable from AudioCodes can place a separate order for a spare parts item of RS-232 cables (supplied in a kit of 10 cables). The Product Number (P/N) for this kit is ***PicoBlade-Serial***.

> **Note:** As part of the continual improvement and development of the Mediant 800, the RS-232 interface has been changed to a standard RJ-45 connector. All Mediant 800 devices with the marketing name, "Mediant 800B" will include this connector. The Product Number (P/N) of the RS-232 kit for the Mediant 800B is ***RJ45-Dtype9-Serial***.

AudioCodes Inc.
27 World's Fair Drive, Somerset, NJ 08873
Tel: +1-732-469-0880 Fax: +1-732-496-2298

International Headquarters
1 Hayarden Street, Airport City, Lod 70151
P.O. Box 255, Ben Gurion Airport, Israel, 70100
Tel: +972-3-976-4000 Fax: +972-3-976-4040

Contact
www.audiocodes.com/info
Website: www.audiocodes.com