

Product Notice No. 149

Cumulative Update 5 for Survivable Branch Appliance Release Announcement

Notice Type:

This Product Notice is **External**.

Notice Subject:

Microsoft released Cumulative Update 5 (CU5) for Lync 2010

Notice Date:

April 2012

Notice Effective Date:

April 2012


Notice Details:

A new update (CU5) is now available for download.

Note – before applying CU05 ensure that the SBA GUI is version 1.1.10.23 (the version appears in the Login screen). If the GUI version is version 1.1.10.23, you can skip the next section. If not please upgrade the SBA GUI according to the steps described below (GUI upgrade does not require an SBA reset).

Upgrading the SBA GUI

1. From AudioCodes support site (need to be logged in), download the new SBA GUI ZIP file (SBA_1_1_10_23).
2. In the SBA web GUI go to Tools -> system upgrade, browse to the ZIP file, and upload the file (same way as for an SBA upgrade).
3. On completion user will get the new Logon screen (make sure that the new version is shown as appears in the below image) .





Apply CU05 to the SBA

User should download the following files from the Microsoft website:


<http://www.microsoft.com/download/en/details.aspx?id=11551>

- OCSCore.msp
- MediationServer.msp
- Server.msp
- UcmaRuntime.msp

1. In the SBA web GUI go to Tools -> system upgrade and browse to the download Microsoft files (.msp), then upload and apply them one by one.



2. After the upgrade you can see in the GUI that the file version has changed.



3. No reset is needed.

Affected Product Family / Part Numbers:

- Mediant 2000 SBA
- Mediant 1000B SBA
- Mediant 800 SBA