

Product Notice #0256

FXS Interface Component Replacement for AudioCodes Mediant™ Product Line

Notice Subject

The FXS Subscriber Line Interface Circuit (SLIC) component on AudioCodes Mediant product line with analog interfaces has reached End-of-Life (EOL) and has been replaced by a later SLIC component version.

Notice Date

September 2015

Notice Effective Date

September 2016

Affected Product Family

- Mediant 1000B
- Mediant 800 and Mediant 800B
- Mediant 500
- Mediant 500L



Note: The affected products listed above include all flavors (E-SBC, Gateway and MSBR).



Notice Details

This Product Notice is an official announcement by AudioCodes that the FXS SLIC component on the Mediant product line with analog interfaces (see Affected Product Family) has reached End-of-Life (EOL).

The FXS SLIC components that are used by Mediant 1000B, Mediant 800/B, Mediant 500 and Mediant 500L were declared by the SLIC component's vendor as EOL. Thus, from September 2016, this Mediant product line will be shipped with an updated FXS component version. This new FXS SLIC component is compatible with the software versions listed in the table below:

Product	Compatible Software Version
Mediant 1000B Gateway/E-SBC	Version 6.8: 6.80A.270.002 and later
·	 Version 7.0: 7.00A.021.004 and later
Mediant 800, Mediant 800B and	 Version 6.8: F6.80A.281.002 and later
Mediant 500 Gateway/E-SBC	 Version 7.0: 7.00A.029.002 and later
Mediant 500L Gateway/E-SBC	7.00A.029.002 and later
Mediant 800/B MSBR and Mediant 500 MSBR	F6.80A.281.002 and later
Mediant 500L MSBR	F6.80A.281.002 and later

Note:



- All software versions support the old FXS SLIC component.
- Customers wishing to purchase any of these products and use them with software versions
 that are **not** compatible with the updated FXS SLIC components, should submit a Last Time Buy
 (LTB) by August 2016.