

# Product Notice #0491



## Component Replacement for AudioCodes MediaPack™ 1288 Analog Blades

This Product Notice is an official notification by AudioCodes of a component replacement for the MediaPack 1288 (MP-1288) Media Gateway analog blades due to supply chain shortages.

As a result of this component replacement, the software version of the MP-1288 was updated and the hardware revision incremented.

### Details

#### Compatible Software Versions

The updated hardware is compatible with the following software versions:

- Long-Term Support (LTS) version: **7.40A.250.908** and later
- Latest Release (LR) version: Will be added to 7.40.500 (planned to May 2023)

#### Identifying the Updated Hardware

The analog blades with the updated components can be identified in the device's INI file and in the output of the CLI command `show system version`. The new hardware revision is indicated by "MI" and the current hardware revision is indicated by "XT", as shown in the example below:

```

;----- HW components -----
; Slot # : Module type : # of ports
;-----
;      1 : FXS (MI)      : 72
;      2 : FXS (XT)      : 72
;      3 : Empty
;      4 : Empty
;-----
    
```

In addition, the hardware revision is indicated on the printed label located on the chassis and blade ("REV").

The MP-1288 devices and blade CPNs, and their corresponding hardware revisions are listed in the table below:

	Customer Part Number (CPN)	HW Unique Identifier	Old HW Revision	New HW Revision
Devices	MP1288-288S-2AC	GTPM01021	P05	P06
	MP1288-216S-2AC	GTPM01025	P05	P06
	MP1288-144S-2AC	GTPM01026	P06	P07
	MP1288-72S-2AC	GTPM01030	P05	P06
	MP1288-288S-2DC	GTPM01101	P05	P06
	MP1288-216S-2DC	GTPM01100	P03	P04
	MP1288-144S-2DC	GTPM01119	P01	P02
	MP1288-72S-2DC	GTPM01145	P01	P02
	MP1288-72S-2AC-TAA	GTPM01167	P2	P03
FXS Blades	FRU-MP1288-FXS-BLD	GTPM01027	P04	P05
	FRU-MP1288-BLD-TAA	GTPM01166	P01	P02

- Notes:**
- The MP-1288 can be installed with a combination of current and new blade hardware revisions. However, the MP-1288 must run a compatible software version for the new blades to be operational.
  - Software versions earlier than the compatible version don't support the new hardware and therefore, must not be loaded to the new MP-1288 hardware revision.

### Effective Date

Immediate (from January 2023, MP-1288 will be shipped with the new hardware revision).

### Affected Products

MP-1288 and Standalone FXS Blades.

### Announcement Date

December 29, 2022.



If you have any questions, contact us at  
<https://www.audiocodes.com/corporate/offices-worldwide>

AudioCodes Ltd. | 1 Hayarden Street | Airport City | Lod | Israel | +972-3-976-4000

Join our mailing list for news and updates