



Product Notice No: 0103

AudioCodes Releases Software Version 3.0.1 for MP-2xx

A. Notice Subject

AudioCodes has officially released Software Version 3.0.1, which introduces new features and new product configurations.

B. Notice Date

July 20, 2010

C. Notice Details

AudioCodes has officially released version 3.0.1 on supported products. The 3.0.1 software release bundle (including Release Notes, User Manuals, and other documentation) is located on the Support page at <http://www.audiocodes.com/downloads>. In general, Version 3.0.1 will replace Version 3.0.0 on future production units. Upgrades to version 3.0.1 are available to customers for a fee and are free to registered customers, who have purchased AudioCodes' Enhanced Support package.

There are 3 separate firmware files as follows:

1. For the MP-20xB.
2. For the MP-202C-A.
3. For the MP-202C-R and MP-202C-W.

Note that when upgrading from software version 2.6.4 to 3.0.x, MP-20xB automatically restores to factory defaults.

D. Affected Products*

Model	FXSFXO	WAN	LAN	WiFi
MP201-B	1	-	1	-
MP202-B	2	-	1	-
MP203-B*	2	1	1	-
MP204-B	4	-	1	-
MP202C-A	2	-	1	-
MP202C-R	2	-	4	-
MP202C-W	2	-	4	802.11b/g

*MP203 has not been approved for Version 3.0.1; 3.0.0_build_13 is the official release.

AudioCodes Inc.

27 World's Fair Drive, Somerset, NJ 08873
Tel:+1-732-469-0880 Fax:+1-732-496-2298

International Headquarters

1 Hayarden Street, Airport City Lod, 70151
P.O. Box 255, Ben Gurion Airport, Israel 70100
Tel: +972-3-976-4000 Fax: +972-3-976-4040

Web Site

www.audiocodes.com