

# **Product Notice #0242**

# **New Hardware Revision for MP-124**

# **Notice Subject**

AudioCodes<sup>™</sup> announces a new hardware revision for its' MediaPack<sup>™</sup> MP-124 VoIP media gateway.

## **Notice Date**

July 2015

# **Notice Effective Date**

October 2015

# **Affected Products**

The new hardware revision applies to MP-124 models based on AC power supply and running the SIP protocol. These include the following CPNs:

- MP124/16S/AC/SIP
- MP124/24S/AC/SIP

The new hardware revision applies to all **new** orders for the above listed products (CPNs) starting from October.



**Note:** The new hardware revision doesn't apply to MP-124 based on DC power supply (MP124/24S/DC/SIP) or to MP-124 running MGCP or MEGACO control protocols (MP124/24S/AC/MGCP).

#### International Headquarters

1 Hayarden Street, Airport City, Lod 7019900 P.O. Box 255, Ben Gurion Airport, Israel, 7019900 Tel: +972-3-976-4000 Fax: +972-3-976-4040 Contact www.audiocodes.com/info Website: www.audiocodes.com



# **Notice Details**

This Product Notice is a formal notification by AudioCodes of the release of a new hardware revision for the MP-124 VoIP media gateway. The current hardware revision (Rev. D) has been replaced by a new hardware revision (Rev. E), which offers the following enhancements and benefits:

- MP-124 Rev. E provides enhanced power surge protection for outdoor FXS cabling. MP-124 Rev. E with Gas Discharge Tube (GDT) for primary protection is ITU-T K.21 basic-compliant, versus MP-124D that requires primary Circa-lightning-protection for ITU-T K.21 basic-compliant.
- MP-124 Rev. E provides a standard RJ-45 connector for RS-232 interface (instead of a DB-9 connector).

# **Affected Software**

The new hardware revision of MP-124 Rev. E is supported from SIP Software Version 6.60A.301 and later. The two hardware revisions—MP-124 Rev. D and MP-124 Rev. E—use different software firmware files (.cmp):

- MP-124 Rev. E: MP124E\_SIP\_F6.60A.301.cmp
- MP-124 Rev. D: MP124\_SIP\_F6.60A.301.cmp

### Notes:

The supported software functionality and configuration of MP-124 Rev. E is identical to MP-124 Rev. D.

MP-124 Rev. D will be continued to be supported and receive software fixes.

#### International Headquarters

1 Hayarden Street, Airport City, Lod 7019900 P.O. Box 255, Ben Gurion Airport, Israel, 7019900 Tel: +972-3-976-4000 Fax: +972-3-976-4040 Contact www.audiocodes.com/info Website: www.audiocodes.com