

# Product Notice #0497



## -- Important Notice --

### xDSL Interface Missing in Mediant 800B MSBR Ver. 7.26A.356.070

Customers using Mediant 800B MSBR for xDSL functionality **must not** upgrade to Version 7.26A.356.070!

Version 7.26A.356.070 doesn't support xDSL interfaces. If Mediant 800B is upgraded to this version, any previously configured xDSL interfaces will no longer appear. Therefore, to avoid loss of configuration and functionality, please upgrade to Version 7.26A.356.074 or later.

Note that for Customers with other MSBR models (Mediant 500L, Mediant 500, or Mediant 800C), Version 7.26A.356.070 is stable and can still be used.

#### Effective Date

Immediate.

#### Affected Products

Mediant 800B MSBR

#### Announcement Date

March 9, 2023.



If you have any questions, at <https://www.audiocodes.com/corporate/offices-worldwide>

AudioCodes Ltd. | 1 Hayarden Street | Airport City | Lod | Israel | +972-3-976-4000

Join our mailing list for news and updates